

## Program Information

|                       |   |
|-----------------------|---|
| Program Name:         | <b>Woodpecker/Flicker Program</b>   |
| Program Information:  | <p>Our service technicians will install two (2) flock reflectors. The first flock reflector will be installed on the roof top peak. The second flock reflector will be installed on the underside of the soffit in the area of concern. The various movements of and reflection of light are meant to deter the woodpeckers/flickers from the area of concern.</p> <p>Up to five (5) holes can be sealed using hardware cloth at the time of initial service.</p> |
| Program Cost:         | \$ 595.00 + GST.  |
| Additional Costs:     | <p>Colour match sealing: Our service technicians will patch the hole using a stucco repair kit and colour match it as required.</p> <p>\$ 355.00 + GST 1-5 holes</p> <p>\$ 455.00 + GST 6-10 holes</p>  |
| Program Term:         | <p>We can't guarantee future damage caused by woodpeckers/flickers. Any new holes created can be repaired at cost.</p> <p>Because the woodpecker flashers are a deterrent, verses a physical barrier there is no guarantee for this product.</p>  |
| Health & Safety:      | The service technician on site will explain any site-specific health & safety concerns at the time of the service.  |
| Payment Information:  | <p>We require a credit card number at time of booking to hold your appointment.</p> <p>We also accept cash, cheque, and interac-e-transfers at time of payment.</p>   |
| Warranty/Limitations: | We stand behind all our work. Should any problems arise within the timeframe of the program we will return for no extra charge, completely hassle-free.   |
| Cancellation:         | We require one business day notice, or the customer is subject to a cancellation fee of the full amount.  |